

Search...

Schauland, Richard "Buddy" ▾

Inbox New Service Request New Work Order New Inspection New Case Task Manager Designer

PLL Contractors Reports Project Manager Assets GIS

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1406	159 Sunset Cir N, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-1267	4075 US 1 N, Saint Augustine, Florida, 32084	privateprovider	Footings	
<input type="checkbox"/>	BP2022-1622	450 Maralinda Dr, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-0676	46 Weeden St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Pool Final / Alarm	Passed
<input type="checkbox"/>	BP2022-0213	525 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Slab	
<input type="checkbox"/>	BP2022-1716	63 Saragossa St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	PR2021-1328	71 Cortez Ave, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	PR2021-1308	725 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Top Out	
<input type="checkbox"/>	BP2022-1200	79 Lamego Ln, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Insulation	Passed