

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location			Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1113	1 Cordova St, Saint Augustine, Florida, 32084			Final	Failed
<input type="checkbox"/>	PR2021-1475	105 Sunset Cir S, Saint Augustine, Florida, 32080			Lath	Passed
<input type="checkbox"/>	PR2021-1477	109 Sunset Cir S, Saint Augustine, Florida, 32080			Lath	Passed
<input type="checkbox"/>	BP2022-1577	148 Cunningham Ave, Saint Augustine, Florida, 32084			Pre Demo	Passed
<input type="checkbox"/>	BP2022-1577	148 Cunningham Ave, Saint Augustine, Florida, 32084			Demo	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarella Dr, Saint Augustine, Florida, 32095			Slab	Passed
<input type="checkbox"/>	BP2022-1389	170 Pasarella Dr, Saint Augustine, Florida, 32095			Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-0932	18 Cordova St, Saint Augustine, Florida, 32084			Roof In Progress	Failed
<input type="checkbox"/>	BP2022-1582	202 Arpieka Ave, Saint Augustine, Florida, 32080			Roof Final	Passed
<input type="checkbox"/>	BP2022-1573	25 Grant St, Saint Augustine, Florida, 32084			Roof In Progress	Passed
<input type="checkbox"/>	PR2021-0908	278 FIVE ISLAND DR			Building Final	Failed
<input type="checkbox"/>	BP2022-1357	32 Saint Francis St, Saint Augustine, Florida, 32084			Roof In Progress	Failed
<input type="checkbox"/>	BP2022-0819	354 Five Island Dr, Saint Augustine, Florida, 32080			Frame	Passed
<input type="checkbox"/>	BP2022-0819	354 Five Island Dr, Saint Augustine, Florida, 32080			Complete Rough	Failed
<input type="checkbox"/>	BP2022-0938	361 Five Island Dr, Saint Augustine, Florida, 32080			Frame	Passed
<input type="checkbox"/>	BP2022-0938	361 Five Island Dr, Saint Augustine, Florida, 32080			Complete Rough	Failed
<input type="checkbox"/>	PR2021-1999	44 E Park Ave, Saint Augustine, Florida, 32084			Dry Wall	Passed
<input type="checkbox"/>	BP2022-0953	48 John St, Saint Augustine, Florida, 32084			Complete Rough	Passed
<input type="checkbox"/>	BP2022-1333	51 Anderson St, Saint Augustine, Florida, 32084			Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2022-1333	51 Anderson St, Saint Augustine, Florida, 32084			Pool Final / Alarm	Failed

<input type="checkbox"/>	Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1129	586 Pescado Dr, Saint Augustine, Florida, 32095	Final	Passed
<input type="checkbox"/>	BP2022-0215	605 Flagler Crossing Dr, Saint Augustine, Florida, 32084	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-0216	645 Flagler Crossing Dr, Saint Augustine, Florida, 32084	Rough Plumbing	Passed
<input type="checkbox"/>	PR2021-1329	81 Cortez Ave, Saint Augustine, Florida, 32080	Insulation	Passed