

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location			Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1960	100 Menendez Rd, Saint Augustine, Florida, 32080			Mechanical Rough	Failed
<input type="checkbox"/>	PR2021-1960	100 Menendez Rd, Saint Augustine, Florida, 32080			Frame	Failed
<input type="checkbox"/>	PR2021-1960	100 Menendez Rd, Saint Augustine, Florida, 32080			Electrical Cover	Failed
<input type="checkbox"/>	PR2021-1961	102 Menendez Rd, Saint Augustine, Florida, 32080			Electrical Cover	Failed
<input type="checkbox"/>	PR2021-1961	102 Menendez Rd, Saint Augustine, Florida, 32080			Mechanical Rough	Failed
<input type="checkbox"/>	PR2021-1961	102 Menendez Rd, Saint Augustine, Florida, 32080			Frame	Failed
<input type="checkbox"/>	PR2021-0144	131 Marine St, Saint Augustine, Florida, 32084			Insulation	Passed
<input type="checkbox"/>	BP2022-1368	132 Marine St, Saint Augustine, Florida, 32084			Dry Wall	Passed
<input type="checkbox"/>	PR2020-0256	1440 US Highway 1 S, Saint Augustine, Florida, 32084			Sign Electric	Failed
<input type="checkbox"/>	BP2022-0690	157 Blanco St, Saint Augustine, Florida, 32084			Temporary Power Pole	Passed
<input type="checkbox"/>	PR2021-1179	172 Cordova St, Apt 12, Saint Augustine, Florida, 32084			Building Final	Failed
<input type="checkbox"/>	BP2022-1702	172 San Marco Ave, Saint Augustine, Florida, 32084			Electrical Final	Failed
<input type="checkbox"/>	BP2022-1721	18 Baru Rd, Saint Augustine, Florida, 32080			Electrical Final	Passed
<input type="checkbox"/>	PR2021-1021	20 Inlet Pl, Saint Augustine, Florida, 32080			Wall Sheeting	Passed
<input type="checkbox"/>	PR2021-1021	20 Inlet Pl, Saint Augustine, Florida, 32080			Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-1512	217 N Whitney St, Saint Augustine, Florida, 32084			Roof In Progress	Passed
<input type="checkbox"/>	BP2022-0634	245 Riberia St, Saint Augustine, Florida, 32084			Window / Door	Passed
<input type="checkbox"/>	BP2022-0634	245 Riberia St, Saint Augustine, Florida, 32084			Dry In	Partial Pass
<input type="checkbox"/>	PR2021-1481	246 Riberia St, Saint Augustine, Florida, 32084			Electrical Cover	Passed
<input type="checkbox"/>	PR2018-1841	31 Orange St, Saint Augustine, Florida, 32084			Building Final	Passed

<input type="checkbox"/>	Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0389	313 Pescado Dr, Saint Augustine, Florida, 32095	Pool Final / Alarm	Passed
<input type="checkbox"/>	BP2022-1688	319 Alcazar St, Saint Augustine, Florida, 32080	Roof Final	Passed
<input type="checkbox"/>	BP2022-0938	361 Five Island Dr, Saint Augustine, Florida, 32080	Insulation	Passed
<input type="checkbox"/>	BP2022-1153	6 Saint George St, Unit 107, Saint Augustine, Florida, 32084	Plumbing Final	Passed
<input type="checkbox"/>	PR2020-1598	700 Plantation Island Dr S, Saint Augustine, Florida, 32080	Fill Cell / Lintel	Passed
<input type="checkbox"/>	PR2021-1328	71 Cortez Ave, Saint Augustine, Florida, 32080	Insulation	Passed
<input type="checkbox"/>	BP2022-1566	76 Marine St, Saint Augustine, Florida, 32084	Gas Rough & Pressure	Failed
<input type="checkbox"/>	BP2022-1076	930 Lew Blvd, Saint Augustine, Florida, 32080	Pool Final / Alarm	Passed