

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location			Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1475	105 Sunset Cir S, Saint Augustine, Florida, 32080			Top Out	Passed
<input type="checkbox"/>	BP2022-0686	165 Cordova St, Saint Augustine, Florida, 32084			Electrical Cover	Failed
<input type="checkbox"/>	BP2022-1023	17 Oak St, Saint Augustine, Florida, 32084			Dry Wall	Passed
<input type="checkbox"/>	BP2022-1675	208 Alcazar St, Saint Augustine, Florida, 32080			Fence Final	
<input type="checkbox"/>	BP2022-1512	217 N Whitney St, Saint Augustine, Florida, 32084			Roof Final	Passed
<input type="checkbox"/>	BP2022-0634	245 Riberia St, Saint Augustine, Florida, 32084			Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0634	245 Riberia St, Saint Augustine, Florida, 32084			Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1114	26 Beacon St, Saint Augustine, Florida, 32084			Slab	Passed
<input type="checkbox"/>	BP2022-1694	28 Dr R B Hayling Pl, Saint Augustine, Florida, 32084			Roof Final	Passed
<input type="checkbox"/>	BP2022-1496	32 Avenida Menendez, Saint Augustine, Florida, 32084			Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1022	375 Maralinda Dr, Saint Augustine, Florida, 32095			Pool Final / Alarm	Failed
<input type="checkbox"/>	BP2022-1570	408 Flagler Blvd, Saint Augustine, Florida, 32080			Electrical Final	Passed
<input type="checkbox"/>	BP2022-0212	450 Flagler Crossing Dr, Saint Augustine, Florida, 32084			Rough Plumbing	
<input type="checkbox"/>	BP2022-1714	467 Maralinda Dr, Saint Augustine, Florida, 32095			Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-0751	5 Dr R B Hayling Pl, Saint Augustine, Florida, 32084			Electrical Final	Failed
<input type="checkbox"/>	BP2022-1115	62 Cuna St, Saint Augustine, Florida, 32084			Mechanical Rough	Passed
<input type="checkbox"/>	PR2021-1311	700 Flagler Crossing Dr, Saint Augustine, Florida, 32084			Wall Sheeting	
<input type="checkbox"/>	PR2020-1598	700 Plantation Island Dr S, Saint Augustine, Florida, 32080			Fill Cell / Lintel	Passed
<input type="checkbox"/>	PR2021-1329	81 Cortez Ave, Saint Augustine, Florida, 32080			Dry Wall	Passed
<input type="checkbox"/>	BP2022-0914	83 Weeden St, Saint Augustine, Florida, 32084			Final	Failed

<input type="checkbox"/>	Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1696	83 Weeden St, Saint Augustine, Florida, 32084	Mechanical Final	Failed