

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location			Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2020-1541	1430 Plantation Island Dr S, Saint Augustine, Florida, 32080			Building Final	
<input type="checkbox"/>	PR2020-1541	1430 Plantation Island Dr S, Saint Augustine, Florida, 32080			Electrical Final	
<input type="checkbox"/>	PR2020-1541	1430 Plantation Island Dr S, Saint Augustine, Florida, 32080			Mechanical Final	
<input type="checkbox"/>	PR2020-1541	1430 Plantation Island Dr S, Saint Augustine, Florida, 32080			Plumbing Final	
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095			Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095			Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095			Dry In	Failed
<input type="checkbox"/>	BP2022-1655	158 Lamego Ln, Saint Augustine, Florida, 32095			Gas Final	Passed
<input type="checkbox"/>	PR2021-1019	16 Inlet Pl, Saint Augustine, Florida, 32080			Fill Cell / Lintel	Failed
<input type="checkbox"/>	PR2021-1792	17 Locust St, Saint Augustine, Florida, 32084			Dry In	Passed
<input type="checkbox"/>	BP2022-1740	178 Avenida Menendez, Saint Augustine, Florida, 32084			Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1734	184 Maralinda Dr, Saint Augustine, Florida, 32095			Mechanical Final	Passed
<input type="checkbox"/>	BP2022-0351	27 Fullerwood Dr, Saint Augustine, Florida, 32084			Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-0351	27 Fullerwood Dr, Saint Augustine, Florida, 32084			Roof Sheeting	Failed
<input type="checkbox"/>	BP2022-1496	32 Avenida Menendez, Saint Augustine, Florida, 32084			Wall Sheeting	Failed
<input type="checkbox"/>	BP2022-1199	402 Maralinda Dr, Saint Augustine, Florida, 32095			Insulation	Passed
<input type="checkbox"/>	BP2022-1214	411 Andreas St, Saint Augustine, Florida, 32080			Window / Door	Passed
<input type="checkbox"/>	BP2022-1724	411 Andreas St, Saint Augustine, Florida, 32080			Window / Door	Passed
<input type="checkbox"/>	BP2022-1714	467 Maralinda Dr, Saint Augustine, Florida, 32095			Gas Final	Passed
<input type="checkbox"/>	BP2022-1717	50 Spring St, Saint Augustine, Florida, 32084			Roof In Progress	Passed

<input type="checkbox"/>	Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1704	61 Julia St, Saint Augustine, Florida, 32084	Roof Final	Passed
<input type="checkbox"/>	BP2022-1200	79 Lamego Ln, Saint Augustine, Florida, 32095	Dry In	Passed