

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location			Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1960	100 Menendez Rd, Saint Augustine, Florida, 32080			Mechanical Rough	Failed
<input type="checkbox"/>	PR2021-1960	100 Menendez Rd, Saint Augustine, Florida, 32080			Frame	Passed
<input type="checkbox"/>	PR2021-1960	100 Menendez Rd, Saint Augustine, Florida, 32080			Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1581	1010 Bella Vista Blvd, Apt 130, Saint Augustine, Florida, 32084			Window / Door	Passed
<input type="checkbox"/>	PR2021-1961	102 Menendez Rd, Saint Augustine, Florida, 32080			Electrical Cover	Passed
<input type="checkbox"/>	PR2021-1961	102 Menendez Rd, Saint Augustine, Florida, 32080			Mechanical Rough	Failed
<input type="checkbox"/>	PR2021-1961	102 Menendez Rd, Saint Augustine, Florida, 32080			Frame	Passed
<input type="checkbox"/>	BP2022-0592	105 Islander Dr, Saint Augustine, Florida, 32080			Lath	Passed
<input type="checkbox"/>	BP2022-1366	11 Poinciana Cove Rd, Saint Augustine, Florida, 32084			Slab	Passed
<input type="checkbox"/>	BP2022-0828	14 Anastasia Park Dr, Saint Augustine, Florida, 32080			Wall Sheeting	Passed
<input type="checkbox"/>	PR2021-1019	16 Inlet Pl, Saint Augustine, Florida, 32080			Fill Cell / Lintel	Passed
<input type="checkbox"/>	PR2021-1855	17 Locust St, Saint Augustine, Florida, 32084			Wall Sheeting	Failed
<input type="checkbox"/>	PR2021-1855	17 Locust St, Saint Augustine, Florida, 32084			Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-1639	172 M L King Ave, Saint Augustine, Florida, 32084			Shed Final	Failed
<input type="checkbox"/>	PR2021-2242	211 Lamego Ln, Saint Augustine, Florida, 32095			Building Final	Passed
<input type="checkbox"/>	BP2022-1643	212 Alcazar St, Saint Augustine, Florida, 32080			Frame	Failed
<input type="checkbox"/>	BP2022-1308	234 Coquina Ave, Saint Augustine, Florida, 32080			Window / Door	Passed
<input type="checkbox"/>	BP2022-1732	25 Spring St, Saint Augustine, Florida, 32084			Roof In Progress	Passed
<input type="checkbox"/>	PR2021-1599	3000 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084			Final	Passed
<input type="checkbox"/>	PR2019-0366	3150 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084			Electrical Cover	Passed

<input type="checkbox"/>	Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1751	35 Dufferin St, Saint Augustine, Florida, 32084	Electrical Final	Passed
<input type="checkbox"/>	BP2022-0819	354 Five Island Dr, Saint Augustine, Florida, 32080	Insulation	Passed
<input type="checkbox"/>	BP2022-0953	48 John St, Saint Augustine, Florida, 32084	Insulation	Passed
<input type="checkbox"/>	BP2022-0649	8 Dupont Ln, Saint Augustine, Florida, 32084	Early Power	Passed
<input type="checkbox"/>	BP2022-1696	83 Weeden St, Saint Augustine, Florida, 32084	Mechanical Final	Passed