

Search...

Schauland, Richard "Buddy" ▾

**Inbox    New Service Request    New Work Order    New Inspection    New Case    Task Manager    Designer**

**PLL Contractors    Reports    Project Manager    Assets    GIS**

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Case Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<a href="#">PR2021-1475</a>	105 Sunset Cir S, Saint Augustine, Florida, 32080	Lath	Failed
<input type="checkbox"/>	<a href="#">PR2021-1477</a>	109 Sunset Cir S, Saint Augustine, Florida, 32080	Dry Wall	Passed
<input type="checkbox"/>	<a href="#">PR2021-1477</a>	109 Sunset Cir S, Saint Augustine, Florida, 32080	Lath	Failed
<input type="checkbox"/>	<a href="#">PR2021-2026</a>	167 Riberia St, Saint Augustine, Florida, 32084	Blower Door Test	Passed
<input type="checkbox"/>	<a href="#">PR2021-2025</a>	169 Riberia St, Saint Augustine, Florida, 32084	Blower Door Test	Passed
<input type="checkbox"/>	<a href="#">BP2022-1582</a>	202 Arpieka Ave, Saint Augustine, Florida, 32080	Roof In Progress	Passed
<input type="checkbox"/>	<a href="#">PR2021-1809</a>	99 Bridge St, Saint Augustine, Florida, 32084	Plumbing Final	Passed