

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0094	11 Sanchez Ave, Saint Augustine, Florida, 32084	Dry Wall	Passed
<input type="checkbox"/>	BP2022-1435	141 Oneida St, Saint Augustine, Florida, 32084	Complete Rough	Failed
<input type="checkbox"/>	PR2021-1597	142 King St, Saint Augustine, Florida, 32084	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1307	16 Avenida Menendez, Saint Augustine, Florida, 32084	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-1568	20 Bay View Dr, Saint Augustine, Florida, 32084	Roof Final	Passed
<input type="checkbox"/>	PR2021-2242	211 Lamego Ln, Saint Augustine, Florida, 32095	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-1068	250 Riberia St, Saint Augustine, Florida, 32084	Mechanical Final	Passed
<input type="checkbox"/>	PR2021-1698	28 RED HOUSE CIR	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-1044	35 E San Carlos Ave, Saint Augustine, Florida, 32084	Mechanical Final	Passed
<input type="checkbox"/>	PR2021-2227	407 Maralinda Dr, Saint Augustine, Florida, 32095	Lath	Passed
<input type="checkbox"/>	BP2022-0335	425 Maralinda Dr, Saint Augustine, Florida, 32095	Blower Door Test	Passed
<input type="checkbox"/>	PR2020-1503	58 S Whitney St, Saint Augustine, Florida, 32084	Demo	Passed
<input type="checkbox"/>	BP2022-1200	79 Lamego Ln, Saint Augustine, Florida, 32095	Top Out	Passed
<input type="checkbox"/>	BP2022-0694	8 Atlantic Ave, Saint Augustine, Florida, 32084	Dry Wall	Passed
<input type="checkbox"/>	BP2022-0699	906 Anastasia Blvd, Saint Augustine, Florida, 32080	Service Change	Failed