

Search...

Schauland, Richard "Buddy" ▾

Inbox New Service Request New Work Order New Inspection New Case Task Manager Designer

PLL Contractors Reports Project Manager Assets GIS

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1098	109 Lions Gate Dr, Saint Augustine, Florida, 32080	Roof Final	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095	Slab	Failed
<input type="checkbox"/>	BP2022-1500	18 N Saint Augustine Blvd, Apt 7, Saint Augustine, Florida, 32080	Window / Door	Passed
<input type="checkbox"/>	BP2022-1567	19 Beacon St, Saint Augustine, Florida, 32084	Roof Final	Passed
<input type="checkbox"/>	BP2022-1211	30 Bay View Dr, Saint Augustine, Florida, 32084	Final	Passed
<input type="checkbox"/>	PR2021-2172	38 Dufferin St, Saint Augustine, Florida, 32084	Window / Door	Partial Pass
<input type="checkbox"/>	PR2021-0494	524 Arricola Ave, Saint Augustine, Florida, 32080	Dry Wall	Failed
<input type="checkbox"/>	BP2022-1349	66 Hypolita St, Saint Augustine, Florida, 32084	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1584	7 Marlin Dr, Saint Augustine, Florida, 32080	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-1537	72 N Whitney St, Saint Augustine, Florida, 32084	Shed Final	Passed
<input type="checkbox"/>	BP2022-1656	89 Evergreen Ave, Saint Augustine, Florida, 32084	Roof In Progress	Passed