

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1711	104 Whispering Brook Dr, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1996	105 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1712	106 Whispering Brook Dr, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1995	109 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1714	112 Whispering Brook Dr, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1993	117 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2020-0256	1440 US Highway 1 S, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Sign Electric	Passed
<input type="checkbox"/>	BP2022-1819	15 Fancher Ct, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1819	15 Fancher Ct, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Service Change	Passed
<input type="checkbox"/>	BP2022-1389	170 Pasarela Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1873	317 Flagler Blvd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-0751	5 Dr R B Hayling Pl, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	BP2022-1716	63 Saragossa St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	PR2021-1807	71 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1806	75 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1805	79 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1804	83 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1803	87 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-1184	91 Coquina Ave, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	PR2021-1802	91 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed

	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1925	92 1/2 Evergreen Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Partial Pass
<input type="checkbox"/>	PR2021-1801	95 Red House Cir, Saint Augustine, Florida 32084	rhurry@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-1800	99 Red House Cir, Saint Augustine, Florida 32084	rschauland@staug-ms01	Blower Door Test	Passed