

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1864	10 Davis St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1912	111 Lincoln St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-1367	148 Cunningham Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-1587	155 Cordova St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1823	25 Pine St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	PR2021-0899	25 Pine St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-0751	5 Dr R B Hayling Pl, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	PR2021-1851	58 S WHITNEY ST	smatthews@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-0914	83 Weeden St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Final	Passed