

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0978	1000 Vista Cove Rd, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-1975	101 Sunset Cir S, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1839	1020 Bella Vista Blvd, Apt 6-104, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-1976	103 Sunset Cir S, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-0739	11 Bonita Bay Dr, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-1434	111 Lincoln St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1951	118 King St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1219	133 Masters Dr, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-0945	146 Inlet Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Window / Door	Failed
<input type="checkbox"/>	BP2022-1367	148 Cunningham Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2022-1863	153 M L King Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-0738	20 Bird Island Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-2030	200 Lions Gate Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	PR2020-1140	207 Spring St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-2032	278 W King St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	PR2019-0223	30 Saint George St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	PR2021-1914	32 E Park Ave, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-2025	34 E Park Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-2047	35 San Marco Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-2044	60 Magnolia Dr, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Plumbing Final	Passed

	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0906	74 Fullerwood Dr, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-1183	98 Saint George St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed