

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Case Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1975	101 Sunset Cir S, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1976	103 Sunset Cir S, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-0828	14 Anastasia Park Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Complete Rough	Passed
<input type="checkbox"/>	PR2021-1792	17 Locust St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Partial Pass
<input type="checkbox"/>	BP2022-1029	18 Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry In	Failed
<input type="checkbox"/>	BP2022-1140	21 Spanish St, Saint Augustine, Florida, 32084		mpratten@staug-ms01	Sign - Non-Electric	Needs 2nd Relnsp
<input type="checkbox"/>	PR2018-1668	24 Ocean Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Miscellaneous	Failed
<input type="checkbox"/>	PR2021-1795	31 Cortez Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-0819	354 Five Island Dr, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	BP2022-0819	354 Five Island Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Building Final	Failed
<input type="checkbox"/>	BP2022-0938	361 Five Island Dr, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-0938	361 Five Island Dr, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	BP2022-0938	361 Five Island Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Building Final	Failed
<input type="checkbox"/>	BP2022-0030	40 Water St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-0635	412 Maralinda Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-1237	5 Atlantic Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Complete Rough	Passed - PP
<input type="checkbox"/>	BP2022-1237	5 Atlantic Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-1461	5 Old Mission Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	PR2020-0058	61 Cortez Ave, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2020-0058	61 Cortez Ave, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Elevation Certificate	Passed

	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2020-0058	61 Cortez Ave, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Building Final	Failed
<input type="checkbox"/>	BP2022-1877	61 Josiah St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-2016	70 Cuna St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1742	927 S Ponce de Leon Blvd, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Passed