

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Case Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1367	148 Cunningham Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-1389	170 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-1029	18 Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	BP2022-1431	1825 Vista Cove Rd, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1604	199 Lamego Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Complete Rough	Failed
<input type="checkbox"/>	PR2021-2030	201 N Whitney St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Failed
<input type="checkbox"/>	BP2022-2011	205 Zoratoa Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Cover	Partial Pass
<input type="checkbox"/>	BP2022-2011	205 Zoratoa Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Plumbing Final	Partial Pass
<input type="checkbox"/>	BP2023-0005	217 Arricola Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-1114	26 Beacon St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-1114	26 Beacon St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-2112	33201 Harbour Vista Cir, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1969	40 Magnolia Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	BP2022-1990	4010 Grande Vista Blvd, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-1528	407 Arricola Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1528	407 Arricola Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	PR2021-1999	44 E Park Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Failed
<input type="checkbox"/>	BP2023-0015	457 Arricola Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2022-1237	5 Atlantic Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	PR2021-1314	880 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Frame	Partial Pass

	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<u>BP2022-0802</u>	95 Dolphin Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Slab	Passed