

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0739	11 Bonita Bay Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2023-0030	123 Pomar St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2022-0050	136 Moore St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Plumbing Final	Failed
<input type="checkbox"/>	BP2022-1604	199 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	PR2021-0039	24 Christopher St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2023-0044	25 Louise St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2023-0036	38 Half Moon Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1267	4075 US 1 N, Saint Augustine, Florida, 32084		privateprovider	Slab	
<input type="checkbox"/>	PR2020-1598	700 Plantation Island Dr S, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	PR2021-1314	880 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Frame	
<input type="checkbox"/>	BP2022-0802	95 Dolphin Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Open Floor Frame	Passed