

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Case Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1661	112 Palmer St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Partial Pass
<input type="checkbox"/>	BP2023-0052	115 Sunset Cir S, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1826	121 Paloma Pt, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Final	Partial Pass
<input type="checkbox"/>	BP2022-2027	15 Fancher Ct, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	BP2022-2116	151 Nesmith Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-0069	20 Bird Island Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	PR2021-2085	209 WHISPERING BROOK DR		smatthews@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2022-1140	21 Spanish St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Sign - Non-Electric	Passed
<input type="checkbox"/>	BP2022-1783	24 Hannah Cole Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Window / Door	Partial Pass
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Fill Cell / Lintel	Failed
<input type="checkbox"/>	BP2023-0006	306 Arredondo Ave, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1941	32 Comares Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2022-1977	3372 Lewis Speedway, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1482	44 E Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	BP2023-0015	457 Arricola Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-0953	48 John St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-0706	58 Pasarela Dr, Saint Augustine, Florida, 32095		rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	BP2022-0215	605 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-0216	645 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1988	74 N Saint Augustine Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Passed

	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0073	76 Coquina Ave, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2023-0031	85 1/2 Douglas Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-0713	86 Pasarela Dr, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	PR2021-1314	880 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Top Out	Passed
<input type="checkbox"/>	BP2022-1900	90 Leeward Island Dr, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	PR2021-1315	940 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Electrical Cover	Passed
<input type="checkbox"/>	PR2021-1315	940 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Frame	Passed