

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-2091	100 Anastasia Lakes Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-2091	100 Anastasia Lakes Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-1366	11 Poinciana Cove Rd, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-1366	11 Poinciana Cove Rd, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-1033	111 Colon Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Complete Rough	Failed
<input type="checkbox"/>	BP2022-2056	118 Amarante Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2022-1009	1430 Plantation Island Dr S, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Sign Electric	Failed
<input type="checkbox"/>	BP2022-1009	1430 Plantation Island Dr S, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Final	Failed
<input type="checkbox"/>	BP2022-0629	144 Twine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Shed Final	Failed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Slab	Passed
<input type="checkbox"/>	PR2021-2225	16 Inlet Pl, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	PR2021-1792	17 Locust St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	PR2021-2223	18 Inlet Pl, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	PR2021-2226	20 Inlet Pl, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	BP2022-2010	21 Hypolita St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Demo	Passed
<input type="checkbox"/>	BP2023-0064	21 Hypolita St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-1876	236 Nesmith Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Window / Door	Failed
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Fill Cell / Lintel	Failed
<input type="checkbox"/>	PR2021-2172	38 Dufferin St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2022-1956	3912 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Plumbing Final	Failed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-2009	409 Arredondo Ave, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	BP2023-0032	44 Atlantic Ave, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1622	450 Maralinda Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-0214	575 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-1224	63 Smith St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Complete Rough	Partial Pass-PP
<input type="checkbox"/>	PR2021-1311	700 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Dry Wall	Passed
<input type="checkbox"/>	BP2022-1820	93 Pasarela Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-1820	93 Pasarela Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Complete Rough	Passed