

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0047	110 Bridge St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1921	14 Masters Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Pre Demo	Passed
<input type="checkbox"/>	BP2022-1484	1440 US Highway 1 S, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-2065	152 Frontera Dr, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-0122	20 Davis St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1684	286 W King St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	PR2019-0366	3150 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1942	327 Saint George St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2023-0078	38 Grant St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1911	39 Masters Dr, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1911	39 Masters Dr, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-1911	39 Masters Dr, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1637	425 Maralinda Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Final	Failed
<input type="checkbox"/>	BP2023-0116	6 Palm Row, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-0216	645 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Frame	Passed
<input type="checkbox"/>	BP2022-1821	725 Flagler Crossing Dr, Saint Augustine, Florida, 32085		privateprovider	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	BP2022-0974	75 A Palmer St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-0974	75 A Palmer St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-0974	75 A Palmer St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-1614	75 Comares Ave Unit 3C, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Final	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0104	8 Nelmar Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0115	962 Fish Island Pl, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Plumbing Final	Passed