

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1477	109 Sunset Cir S, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Blower Door Test	Partial Pass
<input type="checkbox"/>	BP2022-2027	15 Fancher Ct, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	PR2021-1978	168 M L King Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2023-0202	215 W King St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1487	24 Solano Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1609	26 Sebastian Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Partial Pass
<input type="checkbox"/>	BP2022-2095	278 W King St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-2095	278 W King St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1654	3 Aviles St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	PR2019-0366	3150 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	PR2019-0366	3150 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Plumbing Final	Partial Pass
<input type="checkbox"/>	BP2023-0214	317 Anastasia Blvd, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-0221	367 FIVE ISLAND DR SAINT AUGUSTINE 32080		rhurry@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1267	4075 US 1 N, Saint Augustine, Florida, 32084		privateprovider	Wall Sheeting	Passed
<input type="checkbox"/>	BP2023-0106	46 Coquina Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	PR2020-1673	5 Prawn St, Saint Augustine, Florida, 32084		privateprovider	Footings	Passed
<input type="checkbox"/>	BP2022-1725	57 Bay View Dr, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Failed
<input type="checkbox"/>	BP2022-0215	605 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Frame	Passed
<input type="checkbox"/>	PR2021-1317	740 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Slab	Passed
<input type="checkbox"/>	PR2021-1318	770 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Slab	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1319	780 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Slab	Passed
<input type="checkbox"/>	PR2021-1320	840 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Slab	Passed