

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0705	10 Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	PR2021-1477	109 Sunset Cir S, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Elevation Certificate	Failed
<input type="checkbox"/>	PR2021-1477	109 Sunset Cir S, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	PR2021-1477	109 Sunset Cir S, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-1881	110 Arredondo Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Plumbing Final	Failed
<input type="checkbox"/>	BP2022-1908	161 Ancient Island Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-0633	221 N Whitney St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1876	236 Nesmith Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-1258	259 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-1238	33 Casanova Rd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Slab	Failed
<input type="checkbox"/>	BP2023-0219	346 Five Island Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1599	50 Marine St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1599	50 Marine St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0909	544 Pantano Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2022-1395	55 Cortez Ave, Saint Augustine, Florida 32080		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-0907	565 Pantano Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2023-0130	85 N Saint Augustine Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-0959	89 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	PR2021-1607	915 S Ponce de Leon Blvd, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<u>BP2022-1836</u>	961 Lew Blvd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Window / Door	Failed