

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1557	102 South St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-1367	148 Cunningham Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Partial Pass
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-1502	188 Riberia St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-1987	199 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2022-1609	26 Sebastian Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1609	26 Sebastian Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Fill Cell / Lintel	Failed
<input type="checkbox"/>	BP2023-0236	304 Arpieka Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Plumbing Final	Failed
<input type="checkbox"/>	PR2019-0018	308 S Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-1941	32 Comares Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0212	33 Rohde Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1880	33 Vega Ct, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Siding	Passed
<input type="checkbox"/>	BP2022-1880	33 Vega Ct, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-1880	33 Vega Ct, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-1267	4075 US 1 N, Saint Augustine, Florida, 32084		privateprovider	Slab	Passed
<input type="checkbox"/>	BP2023-0213	50 Charlotte St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Not Ready
<input type="checkbox"/>	BP2022-1501	6 Poinciana Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Slab	Failed
<input type="checkbox"/>	BP2023-0096	64 Valencia St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Final	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2021-1314	880 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Insulation	Passed
<input type="checkbox"/>	BP2022-1996	89 DE Haven St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Final	