

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0201	1070 Bella Vista Blvd, #12, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	PR2021-1477	109 Sunset Cir S, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-0739	11 Bonita Bay Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-0739	11 Bonita Bay Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-0702	11 Magnolia Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-0701	11 Magnolia Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-0702	11 Magnolia Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2022-1367	148 Cunningham Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1545	16 Florida Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Failed
<input type="checkbox"/>	BP2022-2067	2 McWilliams St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-0123	22 Hope St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2022-1074	31 John St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	BP2022-1970	318 Arricola Ave, Apt 103, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Building Final	Failed
<input type="checkbox"/>	PR2021-1220	320 Ribault St, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Final	Failed
<input type="checkbox"/>	PR2021-1220	320 Ribault St, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-0219	346 Five Island Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	BP2023-0209	35 Treasury St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-0349	4 McWilliams St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Blower Door Test	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0349	4 McWilliams St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Building Final	Failed
<input type="checkbox"/>	BP2022-1268	4065 US 1 N, Saint Augustine, Florida, 32084	privateprovider	Frame	Partial Pass
<input type="checkbox"/>	BP2022-1599	50 Marine St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-0216	645 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Insulation	Passed
<input type="checkbox"/>	BP2022-1774	95 Cordova St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Final	Passed