

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0411	10 Tremerton St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-1564	118 Carrie Johnson Way, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-1128	137 Lamego Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-1726	150 Pelican Reef Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Dock Final	Failed
<input type="checkbox"/>	2017-0571	164 Avenida Menendez, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-2054	17 Locust St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Gas Rough & Pressure	Failed
<input type="checkbox"/>	BP2023-0257	174 Avenida Menendez, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0097	213 W King St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-0656	217 Alcazar St, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	PR2021-1451	217 Alcazar St, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0278	2400 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-0634	245 Riberia St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	BP2023-0191	277 S Matanzas Blvd, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-2095	278 W King St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	BP2022-2114	28 Magnolia Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2023-0145	286 W King St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	BP2022-1151	3 Marlin Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Window / Door	Failed
<input type="checkbox"/>	BP2022-0799	36 S Whitney St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	PR2021-2172	38 Dufferin St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-2172	38 Dufferin St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Elevation Certificate	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1268	4065 US 1 N, Saint Augustine, Florida, 32084	privateprovider	Top Out	Passed
<input type="checkbox"/>	BP2022-2045	49 Islander Ct, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Rough Plumbing	
<input type="checkbox"/>	BP2022-1640	544 Pantano Dr, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	BP2022-0214	575 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Top Out	Passed
<input type="checkbox"/>	BP2022-0214	575 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Electrical Cover	Passed
<input type="checkbox"/>	PR2019-0901	68 Comares Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	PR2020-1252	79 Masters Dr, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Fire Wall	Passed