

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<a href="#">BP2022-0572</a>	103A Kings Ferry Way, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	<a href="#">PR2021-0699</a>	110 Moore St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	<a href="#">BP2022-2056</a>	118 Amarante Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	<a href="#">BP2022-2056</a>	118 Amarante Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	<a href="#">BP2022-2056</a>	118 Amarante Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	<a href="#">BP2022-2065</a>	152 Frontera Dr, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	<a href="#">BP2022-0357</a>	29 Masters Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Pre Demo	Passed
<input type="checkbox"/>	<a href="#">BP2022-1268</a>	4065 US 1 N, Saint Augustine, Florida, 32084		privateprovider	Electrical Cover	
<input type="checkbox"/>	<a href="#">BP2022-1267</a>	4075 US 1 N, Saint Augustine, Florida, 32084		privateprovider	Insulation	
<input type="checkbox"/>	<a href="#">BP2022-1599</a>	50 Marine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Service Change	Not Ready
<input type="checkbox"/>	<a href="#">BP2022-1501</a>	6 Poinciana Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	<a href="#">BP2022-1501</a>	6 Poinciana Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	<a href="#">BP2022-2081</a>	74 King St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Partial Pass
<input type="checkbox"/>	<a href="#">BP2022-1127</a>	78 Amarante Ln, Saint Augustine, Florida, 32095		rschauland@staug-ms01	Blower Door Test	Passed