

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0702	11 Magnolia Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2022-0701	11 Magnolia Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-0701	11 Magnolia Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2022-1360	167 Sunset Cir N, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-0806	17 Locust St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2022-1639	172 M L King Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Shed Final	Failed
<input type="checkbox"/>	BP2023-0266	217 Arricola Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2023-0154	24 S Leonardi St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2023-0154	24 S Leonardi St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	BP2023-0264	32 Charlotte St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1992	35 Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0285	3531 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0285	3531 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1267	4075 US 1 N, Saint Augustine, Florida, 32084		privateprovider	Insulation	Partial Pass
<input type="checkbox"/>	BP2022-1267	4075 US 1 N, Saint Augustine, Florida, 32084		privateprovider	Electrical Cover	Partial Pass
<input type="checkbox"/>	BP2023-0298	446 Arricola Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-0214	575 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-0126	68 Amarante Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2022-1350	70 Hypolita St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Top Out	Partial Pass

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<u>BP2022-2081</u>	74 King St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Fire Wall	Partial Pass