

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0296	10 Hawksbill Ln, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	PR2021-1960	100 Menendez Rd, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	PR2021-1961	102 Menendez Rd, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2023-0198	11 Cadiz St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	PR2021-0619	110 Cedar St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2022-2034	13 Douglas Ave, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-0363	160 Ancient Island Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1908	161 Ancient Island Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Pool Final / Alarm	Passed
<input type="checkbox"/>	BP2022-1866	239 San Marco Ave, Saint Augustine, Florida, 32084		cboles@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-0634	245 Riberia St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-0839	28 Hildreth Dr, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	PR2021-0839	28 Hildreth Dr, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	PR2021-0839	28 Hildreth Dr, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1196	300 Big Joe Ln, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1496	32 Avenida Menendez, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2023-0264	32 Charlotte St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1868	34 Granada St, Saint Augustine, Florida, 32084		cboles@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-2099	39 Masters Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-0349	4 McWilliams St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2023-0239	427 Anastasia Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0298	446 Arricola Ave, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-0751	5 Dr R B Hayling Pl, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	PR2018-1112	57 Marine St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2023-0226	59 N Saint Augustine Blvd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-0364	595 Pantano Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Gas Rough & Pressure	Failed
<input type="checkbox"/>	BP2023-0116	6 Palm Row, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	2015-0952	62 Spanish St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2023-0157	69 Guanahani Trl, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-1671	72 Oneida St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Top Out	Partial Pass
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Partial Pass
<input type="checkbox"/>	BP2023-0290	8 Dr R B Hayling Pl, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1776	97 M L King Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed