

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0228	1 Saint Andrews Ct, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0228	1 Saint Andrews Ct, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-0411	10 Tremerton St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-0739	11 Bonita Bay Dr, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1434	111 Lincoln St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1434	111 Lincoln St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-0168	115 Bridge St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-0168	115 Bridge St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0168	115 Bridge St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-0168	115 Bridge St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Partial Pass
<input type="checkbox"/>	BP2023-0233	141 Sunset Cir S, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-0234	143 Sunset Cir S, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1367	148 Cunningham Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-0245	160 Blanco St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2022-0408	20 Davis St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-0204	23 Sevilla St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Fence Final	Passed
<input type="checkbox"/>	BP2022-1258	259 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Frame	Partial Pass
<input type="checkbox"/>	BP2022-1609	26 Sebastian Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	PR2021-0839	28 Hildreth Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	PR2020-0150	2800 N PONCE DE LEON		rhurry@staug-ms01	Electrical Final	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	PR2019-0366	3150 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-1199	402 Maralinda Dr, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-1199	402 Maralinda Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-1268	4065 US 1 N, Saint Augustine, Florida, 32084	privateprovider	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0212	450 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0212	450 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Top Out	Passed
<input type="checkbox"/>	BP2022-0212	450 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1501	6 Poinciana Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-0180	63 Bird Island Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-0157	69 Guanahani Trl, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	PR2021-2206	78 Sanford St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Frame	Passed
<input type="checkbox"/>	PR2021-2206	78 Sanford St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	PR2021-2206	78 Sanford St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	PR2021-2206	78 Sanford St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	PR2020-1252	79 Masters Dr, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Insulation	Partial Pass
<input type="checkbox"/>	BP2023-0195	825 Anastasia Blvd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1600	89 Saint Francis St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2022-1776	97 M L King Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed