

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0217	1 Solano Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2023-0217	1 Solano Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2023-0217	1 Solano Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2023-0217	1 Solano Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-0392	10 Mc Millan St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-0392	10 Mc Millan St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-0430	1045 Anastasia Blvd, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-0905	1080 Bella Vista Blvd, Apt 206, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-0690	157 Blanco St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Plumbing Final	
<input type="checkbox"/>	BP2022-0690	157 Blanco St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Mechanical Final	
<input type="checkbox"/>	BP2022-0690	157 Blanco St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Final	
<input type="checkbox"/>	BP2022-0690	157 Blanco St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Building Final	
<input type="checkbox"/>	BP2022-0690	157 Blanco St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2023-0746	1690 US Highway 1 S, Ste B, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-0305	211 Lamego Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2023-1049	22 Marine St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-2113	31 Fullerwood Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Final	Failed
<input type="checkbox"/>	BP2023-1079	37 Bay View Dr, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-0480	404 Flagler Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Footings	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1033	416 Arredondo Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Mechanical Final	Failed
<input type="checkbox"/>	BP2023-1102	42 Lovett St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-1095	42 Nesmith Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-1077	42 Valencia St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-0742	473 Maralinda Dr, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2022-1239	56 Grove Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	BP2023-0413	58 Amarante Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-0413	58 Amarante Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2023-0413	58 Amarante Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-0413	58 Amarante Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-1024	66 Colon Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Top Out	Partial Pass
<input type="checkbox"/>	BP2023-0423	99 Lamego Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-0423	99 Lamego Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2023-0423	99 Lamego Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-0423	99 Lamego Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Mechanical Rough	Passed