

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0393	111 Washington St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-0503	117 Amarante Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2023-0750	2 E Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-0750	2 E Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2023-0750	2 E Park Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-1595	2 Sanchez Cv, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-1595	2 Sanchez Cv, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-1595	2 Sanchez Cv, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-1595	2 Sanchez Cv, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-0750	22 Grove Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	PR2021-0013	34 Park Terrace Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Electrical Final	Partial Pass
<input type="checkbox"/>	BP2023-0924	4010 Grande Vista Blvd, Apt 112, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-1102	42 Lovett St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0691	78 M L King Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-0691	78 M L King Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-0691	78 M L King Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<u>BP2022-1407</u>	97 Anderson St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	<u>BP2023-1027</u>	Harbour Vista Cir, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof In Progress	Passed