

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1268	1 Anastasia Blvd, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-0411	10 Tremerton St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1359	100 Woodcrest Dr, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-1360	100 Woodcrest Dr, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1633	130 Shipyard Way, Saint Augustine, Florida, 32084	privateprovider	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-1367	148 Cunningham Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Elevation Certificate	Failed
<input type="checkbox"/>	BP2023-0717	16 Sidney St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2022-0095	18 Beacon St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-0095	18 Beacon St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Elevation Certificate	Failed
<input type="checkbox"/>	BP2022-0095	18 Beacon St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-0095	18 Beacon St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	BP2023-0668	22 Grove Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-1352	24 Menendez Rd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2023-0631	25 Madeore St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2023-1313	333 Charlotte St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Rough Plumbing	Partial Pass
<input type="checkbox"/>	BP2023-1242	34 Magnolia Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2023-1220	35 Masters Dr, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-1274	41 Rohde Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2022-0211	430 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Early Power	Passed
<input type="checkbox"/>	BP2022-1599	50 Marine St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Dry Wall	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1239	56 Grove Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	BP2023-1298	61 Sanford St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-0146	81 Bridge St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2023-1034	Harbour Vista Cir, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof In Progress	Passed