

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0984	1 Indian Mound Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-2084	10 First St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-2084	10 First St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry In	Failed
<input type="checkbox"/>	BP2022-2084	10 First St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-2084	10 First St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-0937	110 Palmer St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-0503	117 Amarante Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Lath	Passed
<input type="checkbox"/>	BP2022-1493	119 Gaillardia Loop, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-1211	131 Marine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Gas Rough & Pressure	Failed
<input type="checkbox"/>	BP2022-1245	206 Herada St, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Frame	Failed
<input type="checkbox"/>	BP2022-1245	206 Herada St, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Final	
<input type="checkbox"/>	BP2023-1393	233 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1258	259 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	BP2023-0484	411 Arredondo Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1395	55 Cortez Ave, Saint Augustine, Florida 32080		smatthews@staug-ms01	Lath	Passed
<input type="checkbox"/>	BP2023-1252	64 Lighthouse Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-2077	76 Anderson St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Failed
<input type="checkbox"/>	BP2023-1074	8 Park Terrace Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-1074	8 Park Terrace Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Final	Failed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<u>BP2023-1074</u>	8 Park Terrace Dr, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Building Final	Failed
<input type="checkbox"/>	<u>BP2023-1407</u>	8 Pellicer Ln, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	<u>BP2023-0915</u>	88 Marine St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Final	Passed