

Search...

Schauland, Richard "Buddy" ▾

Inbox New Service Request New Work Order New Inspection New Case Task Manager Designer

PLL Admin PLL Contractors Reports Project Manager Assets GIS DigEplan

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1385	104 Gaspar St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Demo	Passed
<input type="checkbox"/>	BP2022-1415	115 Inlet Dr, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1502	188 Riberia St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Elevation Certificate	Failed
<input type="checkbox"/>	BP2022-1503	190 Riberia St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Elevation Certificate	Failed
<input type="checkbox"/>	PR2021-2030	201 N Whitney St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Mechanical Final	Failed
<input type="checkbox"/>	BP2023-1144	239 Pasarela Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1829	33 Old Mission Ave, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-1571	46 Macaris St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Final	Passed
<input type="checkbox"/>	PR2021-2212	64 Dumas St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Building Final	Failed