

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0342	10 Magnolia Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2023-1562	15 Nelmar Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-1050	15 Pine St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0717	16 Sidney St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-1163	180 Tesoro Ter, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2023-1294	215 Lions Gate Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	BP2023-0631	25 Madeore St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-1513	320 Charlotte St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2023-1159	37 Lovett St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	PR2021-1309	375 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Early Power	Passed
<input type="checkbox"/>	BP2022-1369	395 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Early Power	Failed
<input type="checkbox"/>	BP2022-0677	4 Bonita Bay Dr, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2023-1554	4 Clark St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-0917	43 Cordova St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2022-0376	47 San Marco Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	BP2023-1157	53 Marine St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-1515	54 1/2 Carrera St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Partial Pass
<input type="checkbox"/>	BP2022-1501	6 Poinciana Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-1501	6 Poinciana Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1501	6 Poinciana Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Electrical Final	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1501	6 Poinciana Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2023-1344	68 Comares Ave, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	PR2021-1310	711 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Frame	Passed
<input type="checkbox"/>	PR2021-1310	711 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-0906	74 Fullerwood Dr, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1338	Harbour Vista Cir, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof In Progress	Passed