

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1428	1000 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Final	Failed
<input type="checkbox"/>	BP2023-1439	115 Washington St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Shed Final	Failed
<input type="checkbox"/>	BP2023-1481	129 Washington St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2023-1061	137 Pasarela Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1061	137 Pasarela Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2023-1061	137 Pasarela Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Frame	Failed
<input type="checkbox"/>	BP2023-1061	137 Pasarela Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-1061	137 Pasarela Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2023-1061	137 Pasarela Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Early Power	Failed
<input type="checkbox"/>	BP2023-1617	156 Blanco St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0717	16 Sidney St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2023-0717	16 Sidney St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2023-0717	16 Sidney St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-0276	17 Grant St, #A, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-0750	2 E Park Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-0750	2 E Park Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-0750	22 Grove Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	BP2023-1679	244 Coquina Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2023-1261	249 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2023-1261	249 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Roof Sheeting	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1565	249 S Matanzas Blvd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0631	25 Madeore St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2023-0631	25 Madeore St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2023-0631	25 Madeore St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1325	284 Pasarela Dr, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Slab	Passed
<input type="checkbox"/>	BP2023-1686	312 Saint George St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Final	Not Ready
<input type="checkbox"/>	BP2023-1663	35 E San Carlos Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-1159	37 Lovett St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0426	39 Phillips St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-0426	39 Phillips St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-0426	39 Phillips St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-0426	39 Phillips St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2023-0426	39 Phillips St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-1640	4 Sanchez Cv, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-1472	4035 Grande Vista Blvd, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1368	51 Charlotte St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Building Final	Partial Pass
<input type="checkbox"/>	BP2023-1509	65 Pasarela Dr, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Rough Plumbing	Failed
<input type="checkbox"/>	BP2023-1197	79 N Saint Augustine Blvd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Wall Sheeting	Passed